

Products Affected by Upcoming 2022 GPS Rollover

T mess e Fu Rel To:

Wed, Aug 4, 2021 at 12:15 PM

lick here to view this e-mail as a webpage

SERVICE ADVISORY

NOTEWORTHY NEWS FOR FURUNO AUTHORIZED DEALERS AND THEIR TECHNICIANS

Upcoming GPS Rollover Impacts Select Furuno Products

August 4, 2021 Service Advisory #2021-03

Following up on the 2020 bulletin (2020-10T) covering years 2020/2021, this bulletin on the same subject provides notification of various Furuno products that will be affected by GPS Rollover in the coming months. While these devices impacted by GPS Rollover can still provide accurate GPS location after the rollover takes place, a factory reset or power cycle may be required. These units will show and output incorrect date/time after the published period, if not addressed.

We recommend these legacy units be considered for replacement or updated as soon as possible, to ensure proper operation at all times. Updating or replacing these legacy units is particularly important for commercial or business applications.